




# United States Department of the Interior

## BUREAU OF LAND MANAGEMENT FILLMORE FIELD OFFICE

35 East 500 North  
Fillmore, UT 84631  
<http://enbb.blm.interwebdesign.com>



In Reply Refer to:  
3800  
(U-010)  
UTU-075888

August 1, 2001

CERTIFIED MAIL # 7000 1530 0006 2414 9156  
RETURN RECEIPT REQUESTED

JOE DUNLOP  
2236 KARALEE WAY  
SANDY UT 84092

Dear Mr. Dunlop:

On July 19, 2001, a surface compliance inspection was conducted at the site of your Notice serialized UTU-075888, located in T. 12 S., R. 7 W., Section 13.

The inspection revealed no problems, however, it has come to our attention that the BLM serial number for the mining claim was never submitted. 43 CFR 3809.301(b)(1) mandates that this information be included on a Notice.

Within 30 days of receipt of this letter, please submit the required information. If we do not receive it, we will consider the surface disturbance at the site to be reclaimed, and close the case file.

Reclamation for the disturbance in Section 35, T. 12 S., R. 7 W. will remain the responsibility of Resource Design Solutions (RDS), and that case file is serialized UTU-079454. Should RDS default on its responsibility, 43 CFR §3809.598 mandates that "...mining claimants are jointly and severally liable for the remaining costs" of reclamation. Our records indicate that you are one of eight mining claimants on that site.

Please feel free to contact me if you have any questions at (435) 743-3126.

Sincerely,

Larry Garahana  
Geologist

0011

cc: D. Wayne Hedberg, UDOGM (S/023/067)  
Resource Design Solutions, PO Box 1178, Riverton, Utah 84065

RECEIVED

U.S. DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT  
LAND USE AND MINING

**SURFACE INSPECTION  
COMPLIANCE REPORT**

Date of Inspection: July 19, 2001

Case Serial No.: UTU-075888

Operator: Joe Dunlop

Project Description: Mining

Legal Description: NW¼ Sec. 13 T. 12 S., R. 7 W.


Field Office: Fillmore


Inspector: Sheri Wysong

REPORT NARRATIVE (REFERENCE STIPULATIONS BY NUMBER OR TITLE)

There has been no activity at this site for probably a year. The corporation with which Dunlop was associated, Resource Design Solutions, moved to a site about three miles to the south.

The disturbance consists of a few granite boulders that have been drilled and split in preparation for use as building stone. Other than the drill marks on the boulders, there is virtually no disturbance associated with this operation, and the case file could be closed.

  
Signature of Inspector

  
Signature of Authorized Officer